

- 10- hack saw blades
- 1- electric drill 1/4"
- 6- files
- 1- 6" adjustable end wrench
- 1- 1/2" chisel
- 1- combination square
- 1- pr. shears, metal
- 1- pr. shears, grass
- 1- hammer
- 1-100W soldering iron
- 3- metal brushes
- 1- motor 1/4 hp
- 1- mandril/brush and emery wheel
- 1- 6" monitor speaker
- 1- gates 4 channel remote amp.
- 1- extension cord AC
- 2- oil cans
- 1- tube record card file
- 1- magneocorder changeover panel
- 1- stepladder
- 1- dozor type mike stand
- 1- boom extension for Atlas mike stand
- 1- tape recorder base/casters
- 5- army surplus field telephones
- 1- pr. head phones - Trimm
- 1- mike stand- table
- Misc. asst. of adapter cords
- Misc. asst. of wire
- 1- stepladder
- 1- asst. nuts, bolts & washers
- 7- replaceable 30 amp. fuse cartridges
- 4- 60 amp. fuses
- 9- 125 amp. fuses
- 6- 100 amp. fuses
- 1- fuse puller
- 1- IN34A crustal diode
- 6- boxes AG fuse asstd.
- 7- spare meters
- 1- mallory rotary switch
- 1- Johnson tube socket
- 1- Bearing puller
- 4- Johnson 104-261 couplings
- 4- receiver type variable condensers
- 1- assortment relay contacts
- 1- asst. 2 Watt resistors approx. 100
- 1- Amperex VC-100 condenser
- 2- Eimac 866 tubes
- 1- New 2 used 8003 tubes 1-891.R tube (spare)
- 1- 813 tube
- 2- RCA 866 tubes 1-892.R Tube (spare)
- 2- RCA 872 tubes
- 1- RCA 813 tubes
- 1- scope tube for phase monitor
- 1- 300 B tube
- 1- 274A tube
- 1- spare relay solenoid
- 1- asst. spare parts for magneocorder