




CARROLL & POLLY G. CHANDLER

S. & W. CO.

WEATHERS CIRCLE

BLAKE P. & DAVID H. GARRETT

Notes:  
 Revision of Subdivision January 13, 1970  
 No Change in Lots 40 Thru 55 & Lot 88.  
 All Lots Have Min. of 80' Frontage or at B.L.  
 Iron Pins at all Corners Unless  
 Otherwise Noted.



# MAP OF STONEWOOD

FOUNTAIN INN, S.C.

1-13-1970  
 R. W. DALTON  
 1-13-1970  
 916  
 JAN. 13, 1970  
 Revision of Revision of January 13, 1970  
 3/12/70  
 Date  
 Approved

## REVISION OF STONEWOOD #13

S. & W. CO. OWNER	DALTON & NEVES, ENGR'S CIVIL & CONSULTING ENGINEERS
NO. OF ACRES 60.67	MILES OF NEW ROADS 1.09
NO. OF LOTS 99	DATE JANUARY 1970
ERROR OF CLOSURE 1/5143	

SCALE 1" = 100'  
 100 0 100 200