

GALLEY:

Location: In deckhouse Type of Stove: L.P. Traveler - 3 burner with oven
 Stove Tank Location: Underboard Spare Tanks: None
 Stove Lines and Regulator: At tank Stove Shut-Offs: At tank
 Insulation Stove: None Stack: None
 Ventilation: Door and windows Hot Water: None
 Refrigeration: None

MACHINERY:

Main Engine: Location: Under deckhouse No. Type: One diesel
 Make: Gray Marine Model: 6-71 Serial: _____
 No. Cyls: Six R. P. M.: 1700 H. P.: 175 Reduct. Gear: Yes Approx. Speed: 10 K.
 Year: 1956 When Overhauled: _____ Condition: Operating good at this
 Engine Bed: None Pan Under Engine: None time.
 Engine Cooling System: Fresh water circulation Ventilation: None - see page 3
 Carburetor; Flame Arrestor: None Blower: None
 Fuel Pump: Yes Bowls: None Filters: Yes
 Exhaust Line: Steel Box Stack - well insulated Cooled: Air
 Exhaust Silencer: Yes
 Engine Generator: Alternator Controls: None
 Shaft Logs, Type: None Stuff. Box: Yes
 Propeller: Four blade bronze Spare: Yes - not aboard
 Propeller Shafts: None Stub Shaft: None
 Struts: Bronze Bearings: Rubber cutless - four months old
 Propeller Protection: None Rudder: Bronze
 Bilge Pumps: Two electric and one main engine driven

ELECTRICAL SYSTEM:

Auxiliary Generator: None Location: _____
 Ventilation: _____ Model: _____ Serial No.: _____ Watts: _____
 Voltage: _____ No. Cyls.: _____ R. P. M.: _____ H. P.: _____
 Exhaust Line: _____ Cooled: _____ Carburetor, Type: _____
 Flame Arrestor: _____ Fuel Pump: _____ Filter: _____ Bowls: _____
 Electrically Driven Equipment: Lights, electronics and electric reels
 Storage Batteries, Engine: 12 Volt 8D in boxes with covers
 Lighting: _____
 Battery Installation: _____
 Wiring: Thermostatic _____ Condition: See page 3
 Switchboard: Yes Fused: Yes Circuit Breaker: No
 Lightning Arrestors: Yes Aerials: Yes Ground: Yes

FIRE FIGHTING EQUIPMENT:

Portable Extinguishers: 2 - 2 1/2 lb. dry chem. and two 15 lb. C-02
 Date of Inspection: _____ Location: Deck, Galley, Forward Cabin, Aft Deck
 Built-In System: _____
 Date of Inspection: _____ Location: _____
 Auxiliary Fire Pump System: _____ Location: _____

TANKS:

Fuel: Diesel No. Capacity: 2-155 gallon Shape: Round
 Material: Steel Location: Aft Deck, port and starboard side
 Condition: Good Secured: Yes
 Filling Lines and Vents: _____
 Overflow and Vents for Outboard: _____ Bonded: No
 Valves: Yes Location: _____ Accessibility: Yes
 Fuel Lines and Connections: _____
 Additional Fuel or Inflammables Carried? L.P. gas for stove
 Water Tanks, No.: One Capacity: 30 gallon
 Location: Top of deck Material: Glass lined steel
 Shape: Round Condition: Good
 Compliance to U.S. Government Requirements Yes
 Please Note Supplemental for Recommendations and Remarks.

Signed without Prejudice

[Signature]

Attending Surveyor

Bill Daniels and Associates Organization, or its representatives, agents or employees, are not to be held responsible for any inaccuracy, omission, misstatement or error in judgement. To all intent, purpose and interest, reports emanating from this office may be adjudged as an evaluated opinion of the attending surveyor.

(CONTINUED ON NEXT PAGE)