



Note:
Improvements on this
lot are not in a flood
hazard area.



PROPERTY OF
MARY MCCARTHY
GREENVILLE, S. C. GREENVILLE CO.
SCALE 1" = 40' 23 FEB 1981



This is to certify that on the 23rd day of February, 1981, I surveyed the property shown on this plat, being known as PROPERTY OF MARY MCCARTHY and recorded in the REC Office Greenville County, S. C., in Plat Book _____ at Page _____; and that the property lines, walls and buildings are as shown hereon, and that the walls and buildings located on said lot do not encroach or project on adjacent street or property, and that no adjacent walls or buildings encroach or project on said premises, and no power lines cross this property except as shown hereon.

24337

R. B. Bruce
R. B. Bruce, REC FEB 22 1981

8-6-84
FEB 27 1981

CAROLINA SURVEYING CO.
112 A Main St.
Greenville, S. C.

GCTO FF27-81 522

3 OCT

FILED
GREENVILLE CO. S. C.
FEB 27 10 32 AM '81
DONNIE S. TANKERSLEY
R.M.C.