

This is to certify that on April 5, 1984, I surveyed the property shown on this plat, known as Lot No. 120 of MAP NO. 2 CAMILLA PARK, as recorded in the RMC Office for Greenville County, in Plat Book M, at page 85, and that the property lines, walls and buildings are as shown hereon, and that the building located on said lot does not project nor encroach on adjacent streets or property, and that no adjacent walls or buildings project nor encroach on said lot, and that no utilities cross this lot.

Except as may be shown hereon. The degree of accuracy is 1/10,000.

NOTE: This property is not located within a flood hazard area.

Survey by: Hichara D. Wooten, Lin Greenwille, South Car

31261

S. C. R. L. 61 410. 1678

Dwg. No. 3350